


## Student Success District Bear Down Gym Preservation & Renovation


Construction Update - Week of October 25th, 2021



Inside the main entrance standing on the historic gym floor, looking south. Sound attenuation panels are being installed on level 3. The historic gym floor on level 2 has been painted. The first lockers have been installed on level 1.










## THE UNIVERSITY of ARIZONA

## Student Success District Bear Down Gym Preservation & Renovation

Construction Update - Week of October 25th, 2021



Lockers in the Community Clubhouse have been installed. More lockers will fill this space next to the steel mirror supports on the left. Check it out!

Also on level 1 the Catering Kitchen has been tiled. Next, the kitchen equipment will arrive!



